



BMW 4 GRAN COUP?: 1JVS912

Vinnnumber:	WBA4D510X0GT64352	Versionname:	2.0 418D (100KW) GRAN COUPE
First Registrationdate:	9/03/2015	Fiscalpower:	
Expertise Mileage:	121219	Power Kw:	100
Bodytype:		Body color:	Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OVER 23000 KM	Parking lot:	1113
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/98 V LightMetal				
Winter tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			977,00
Tailgate, Hail damage, PDR - Hail			173,00



Roof, Hail damage, PDR - Hail

346,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bonnet, Hail damage, PDR - Hail

173,00



Bumper R, Scratch(es), Acceptable

0,00



Alloy rim R L, Chemical polution, LI - Repair and paint (complete)

95,00



Alloy rim F L, Chemical polution, LI - Repair and paint (complete)

95,00

