



**VOLKSWAGEN Transporter: 1CKA038**

Vinnumber:	<b>WV1ZZZ7HZCH054373</b>	Versionname:	<b>TRANSP.1200 B/F SWB 84PK</b>
First Registrationdate:	<b>15/12/2011</b>	Fiscalpower:	
Expertise Mileage:	<b>128215</b>	Power Kw:	<b>62</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1310</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	
Windows electric F	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>No GPS</b>
Type of Lining	<b>Lining artificial leather</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/65/16/101 H Steel</b>			
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>1737,27</b>
Sill outer L, Dent(s), LI - Repair and paint (complete)	<b>232,88</b>



Bumper R, Crack, E - Replace

**329,40**



Sill outer R, Dent(s) and scratch(es), It - Spot repair 115,56



Roof, Dent(s), Acceptable 0,00

*No pictures to display*

Rearlight R , Crack, E - Replace 91,50



Door F L, Scratch(es), Acceptable 0,00

*No pictures to display*

Seat cover F L, Worn, Acceptable 0,00

*No pictures to display*

Wing R R, Scratch(es), LI - Repair and paint (complete) 231,15



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete) 362,02



Bodywork, Not original part, Acceptable 0,00

*No pictures to display*

Trunk lid covering R, Broken, Acceptable 0,00

*No pictures to display*

Bumper moulding F M, Broken, E - Replace 40,00



Door F R, Dent(s), LI - Repair and paint (complete) 334,76

