



BMW 3 GRAN TURISMO: 1LJU722

Vinnumber:	WBA8Y51010G430342	Versionname:	2.0 318D (100KW) GRAN TURISMO
First Registrationdate:	7/10/2015	Fiscalpower:	
Expertise Mileage:	74043	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	IN 20000 KM	Parking lot:	2823
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/97 Y LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 1743,28

Wing R L, Scratch(es), 67 - Polish 0,00

Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Seat cover F L, Worn, P - Check 0,00



Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Wing R R, Repaired, Acceptable 0,00



Door R R, Repaired, P - Check 0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Tailgate, Dent(s) and scratch(es), Le - Replace and paint 1034,68



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Door F R, Repaired, P - Check 0,00



Wing F R, Repaired, Acceptable 0,00



