



BMW 3 BERLINE: 1LEY866

Vinnumber:	WBA8F91090K439686	Versionname:	2.0 316D (85KW) BERLINE
First Registrationdate:	9/09/2015	Fiscalpower:	
Expertise Mileage:	47274	Power Kw:	85
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	UITVOEREN	Parking lot:	3115
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Rear parking sensors	
GPS storage		Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/96 W LightMetal				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	467,08
--------------------------	---------------

Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)	290,08
--	---------------




Roof, Dent(s), PDR - Paintless dent repair 63,00



Maintenance, Maintenance, Execute 0,00



Rearlight L, Broken, E - Replace 114,00



Door panel F R, Scratch(es), Acceptable 0,00

No pictures to display

Door frame F L, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer L, Scratch(es), 67 - Polish 0,00

