



VOLKSWAGEN TIGUAN: 1NAT754

Vinnumber:	WVGZZZ5NZGW544283	Versionname:	2.0 CRTDI 110KW SPORT & STYLE BMT
First Registrationdate:	6/01/2016	Fiscalpower:	
Expertise Mileage:	133666	Power Kw:	110
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4833
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Sun Roof electric	
GPS storage	SD	Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	Tow bar fixed
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/17/96 H LightMetal				
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1032,23
Wheel hub cap F R, Missing, E - Replace	20,00



Wing R R, Scratch(es), 67 - Polish 0,00

No pictures to display

Wing trim R R, Scratch(es), E - Replace 84,00



Door panel R L, Scratch(es), Acceptable 0,00

No pictures to display


Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete) 301,68



Door R L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Door F L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Bumper cover R M, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rear spoiler, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Door trim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	