



**VOLKSWAGEN PASSAT VARIANT: 1LAE901**

Vinnumber:	<b>WVWZZZ3CZGE019828</b>	Versionname:	<b>1.6 TDI VARIANT COMFORTLINE</b>
First Registrationdate:	<b>31/07/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>98073</b>	Power Kw:	<b>88</b>
Bodytype:		Body color:	<b>Dark Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1408</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Seats F heated	Type of Tow bar
Radio multimedia	<b>Tow bar fixed</b>
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/60/16/95 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Semperit: 5 mm</b>	Fr.R.	<b>Semperit: 5 mm</b>
	Re.L.	<b>Semperit: 5 mm</b>	Re.R.	<b>Semperit: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	808,86
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display


Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing R L, Dent(s), It - Spot repair	115,56
-------------------------------------	--------



Roof, Chemical polution, LI - Repair and paint (complete)	481,50
---	--------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display