



**VOLKSWAGEN PASSAT VARIANT: 1LDJ430**

|                                    |                          |              |                                    |
|------------------------------------|--------------------------|--------------|------------------------------------|
| Vinnumber:                         | <b>WVWZZZ3CZGE045293</b> | Versionname: | <b>2.0 TDI VARIANT COMFORTLINE</b> |
| First Registrationdate:            | <b>27/08/2015</b>        | Fiscalpower: |                                    |
| Expertise Mileage:                 | <b>103186</b>            | Power Kw:    | <b>110</b>                         |
| Bodytype:                          |                          | Body color:  | <b>Black</b>                       |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                     |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                   |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                          |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>2624</b>                        |
| Number of doors:                   | <b>5</b>                 |              |                                    |
| Number of seats:                   | <b>5</b>                 |              |                                    |
| Number head rests:                 | <b>5</b>                 |              |                                    |
| Rims summer:                       | <b>Aluminium</b>         |              |                                    |
| Category:                          | <b>Passenger Car</b>     |              |                                    |
| Oil level:                         | <b>OK</b>                |              |                                    |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                    |

**Options**

|                                |                              |                       |                   |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Radio CD                       |                              | Central consol F      |                   |
| GPS storage                    | <b>SD</b>                    | Luggage cover         |                   |
| GPS storage                    |                              | Front parking sensors |                   |
| Windows electric F             |                              | Rear parking sensors  |                   |
| Windows electric R             |                              | Type of Tow bar       | <b>No Tow bar</b> |
| Cruise Control                 |                              |                       |                   |
| Steering wheel multifunctional |                              |                       |                   |
| Seats F heated                 |                              |                       |                   |
| Radio multimedia               |                              |                       |                   |
| Type of headlighting           | <b>Headlighting Xenon</b>    |                       |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |                   |
| Type of Lining                 | <b>Lining leather</b>        |                       |                   |
| Type of climate control        | <b>Autom climate control</b> |                       |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                          |       |                          |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| <b>215/55/17/94 V LightMetal</b> |       |                          |       |                          |
| Summer tyres:                    | Fr.L. | <b>Continental: 3 mm</b> | Fr.R. | <b>Continental: 3 mm</b> |
|                                  | Re.L. | <b>Michelin: 4 mm</b>    | Re.R. | <b>Michelin: 4 mm</b>    |

**Assistance equipment**

|  |            |            |            |
|--|------------|------------|------------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |            |            |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |

Total cost ex VAT 591,00

Wing R R, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim R R polished, Scratch(es), Acceptable 0,00

No pictures to display

|   |       |
|---|-------|
| Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|---|-------|



|  |       |
|--|-------|
| Door F L, Dent(s), PDR - Paintless dent repair | 63,00 |
|--|-------|



|                               |      |
|-------------------------------|------|
| Door R R, Dent(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display

|                                   |      |
|-----------------------------------|------|
| Bumper F, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|                                       |        |
|---------------------------------------|--------|
| Rear window, Scratch(es), E - Replace | 370,00 |
|---------------------------------------|--------|



|  |       |
|--|-------|
| Door R L, Dent(s), PDR - Paintless dent repair | 63,00 |
|--|-------|



|                                   |      |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|                                   |      |
|-----------------------------------|------|
| Bonnet, Stone chip(s), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|   |      |
|---|------|
| Rocker panel inner R R, Scratch(es), Acceptable | 0,00 |
|---|------|

No pictures to display