



CITROEN GRAND C4 PICASSO: 1JLP267

Vinnumber:	VF73A9HC8EJ838390	Versionname:	1.6 E-HDI 115 MAN6 EXCLUSIVE
First Registrationdate:	19/01/2015	Fiscalpower:	
Expertise Mileage:	122852	Power Kw:	85
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4711
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Panoramic roof	
GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar fixed
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/17/95 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment


Emergency spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	2026,90
Door R L; Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Rear spoiler, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Protection plate M, Deformed / Strained, E - Replace

74,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Door F L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display


Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Scratch(es), 67 - Polish 0,00

No pictures to display

Engine protective plate, Deformed / Strained, E - Replace 108,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20





Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00

