



FORD S Max: 1GMV493

Vinnumber:	WF05XXGBWSES32015	Versionname:	S-MAX Titanium Style DPF 136PK
First Registrationdate:	13/03/2014	Fiscalpower:	
Expertise Mileage:	169325	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3112
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Seats electric F R	
GPS storage		Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/45/18/98 Y LightMetal				
Summer tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 1501,05

Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Worn, P - Check 0,00



Alloy rim R R, Deformed / Strained, E - Replace

277,44



Engine protective plate, Not original part, E - Replace

96,49



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Dent(s), Acceptable

0,00

No pictures to display

Wing F R, Dent(s), PDR - Paintless dent repair

63,00



Door frame R L, Dent(s), It - Spot repair

115,56



Bumper R, Deformed / Strained, E - Replace

483,84



Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Tailgate, Scratch(es), It - Spot repair 115,56



Sunroof cover, Broken, Repair/replace (lump sum) 0,00

