



CITROEN C4 Picasso: 1HSV778

Vinnumber:	VF73E9HC8EJ764836	Versionname:	GR.C4 PICASSO Exclusive 115PK
First Registrationdate:	24/09/2014	Fiscalpower:	
Expertise Mileage:	105807	Power Kw:	85
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	11 MAAND	Parking lot:	4422
Maintenance:	22400		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/17/95 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	508,35
-------------------	---------------




Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

<i>No pictures to display</i>		
Door R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim F R polished, Chemical polution, Acceptable		0,00
<i>No pictures to display</i>		
Internal Boot Lining L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door F R, Scratch(es), LI - Repair and paint (complete)		318,35
		
Bumper cover R M, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)		95,00
		
Door R L, Dent(s) and scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Internal Boot Lining R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Outer door handle F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)		95,00
		
Alloy rim R R polished, Chemical polution, Acceptable		0,00
<i>No pictures to display</i>		