



<b>BMW X1: 1KHX746</b>			
Vinnumber:	<b>WBAVP91020VV50143</b>	Versionname:	<b>2.0 XDRIVE20D (120KW)</b>
First Registrationdate:	<b>7/05/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>93899</b>	Power Kw:	<b>120</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>4 Weel</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4821</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

<b>Options</b>			
Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	<b>HD</b>	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	<b>No Tow bar</b>
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>NOT OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>225/45/18/91 Y LightMetal</b>			
Summer tyres:	Fr.L.	<b>Continental: 3 mm</b>	Fr.R.	<b>Continental: 3 mm</b>
	Re.L.	<b>Continental: 3 mm</b>	Re.R.	<b>Continental: 3 mm</b>

<b>Assistance equipment</b>			
Number of charging cables (normal)	<b>0</b>	Runflat	<b>Yes</b>
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>2518,40</b>
<b>Bumper moulding R, Scratch(es), E - Replace</b>	<b>14,40</b>



Alloy rim R L, Scratch(es), I - Repair

50,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Bumper trim R, Scratch(es), E - Replace

184,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Bonnet, Dent(s), PDR - Paintless dent repair

63,00



Alloy rim F L, Scratch(es), I - Repair

50,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Bumper spoiler F, Scratch(es), E - Replace

42,00



Door R L, Scratch(es), LI - Repair and paint (partial)

220,00



Tailgate, Dent(s), LI - Repair and paint (complete)

301,68



Alloy rim F R, Scratch(es), I - Repair

50,00



Maintenance, Maintenance, P - Check

0,00



Reflector, Crack, E - Replace

25,17



Alloy rim R R, Scratch(es), I - Repair

50,00



Wing trim R R, Scratch(es), E - Replace

84,00



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (partial)

220,00



Door trim R R, Deformed / Strained, E - Replace

114,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80

