



**MERCEDES SPRINTER: 1KTR804**

Vinnumber:	<b>WDB9036631R665355</b>	Versionname:	
First Registrationdate:	<b>2/06/2004</b>	Fiscalpower:	
Expertise Mileage:	<b>259169</b>	Power Kw:	<b>95</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>LCV30</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Type of headlighting	<b>Headlighting Halogen</b>	Type of Tow bar	<b>No Tow bar</b>
Type of Lining	<b>Lining fabrics</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/70/15/112 R Steel</b>				
Summer tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>2157,61</b>
--------------------------	----------------

<b>Bumper grille F R, Chemical polution, E - Replace</b>	<b>30,30</b>
----------------------------------------------------------	--------------



<b>Bodywork, Dirty, P - Check</b>	<b>0,00</b>
-----------------------------------	-------------



Wing R L, Rust, LI - Repair and paint (complete)

231,15



Steel rim R L, Scratch(es), Acceptable

0,00

*No pictures to display*

Front end, Dent(s) and scratch(es), LI - Repair and paint (complete)

437,00



Sill outer R, Rust, LI - Repair and paint (complete)

232,88



Sidewall RR (LCV), Rust, LI - Repair and paint (complete)

375,00



Gear shift lever cover, Tear, E - Replace

9,00



Steel rim R R, Scratch(es), Acceptable

0,00

*No pictures to display*

Sliding door R, Rust, LI - Repair and paint (complete)

382,02



Wing F R, Rust, LI - Repair and paint (complete)

85,00



Boot cover, Broken, E - Replace

45,00



Rearlight R , Broken, E - Replace

91,50



Steel rim F L, Scratch(es), Acceptable

0,00

*No pictures to display*

Boot carpet, Scratch(es), Acceptable

0,00



Door F L, Rust, LI - Repair and paint (complete)

238,76

