



FORD Transit 350L: 1FNJ375

Vinnumber:	WF0XXXTTFXDA28704	Versionname:	TRANSIT B/F 350L LWB Amb.DPF(EU5)125PK
First Registrationdate:	28/08/2013	Fiscalpower:	
Expertise Mileage:	191614	Power Kw:	92
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2623
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Type of Tow bar	Tow bar fixed
Windows electric F		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	No GPS	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	NOT OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/75/16/114 R Steel				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	806,35
Trunk door R R, Dent(s), It - Spot repair	163,56



Bumper F, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover R L, Missing, E - Replace	22,50



Windscreen, Crack, E - Replace	0,00
--------------------------------	------



Roof, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Bodywork, Not original part, Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	327,15



Bumper corner R R, Crack, E - Replace	128,00
---------------------------------------	--------



Sliding door R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Roof pillar R, Scratch(es), LI - Repair and paint (complete)	165,14

