



FORD Fiesta: 1GMQ946

Vinnumber:	WFORXXGAKREY46317	Versionname:	FIESTA VAN Ambiente 75PK
First Registrationdate:	12/03/2014	Fiscalpower:	
Expertise Mileage:	161623	Power Kw:	55
Bodytype:		Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4225
Battery functioning:	Yes		
Number of doors:	3		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	
Windows electric F	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/50/15/92 H Steel			
Winter tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2066,12
-------------------	----------------

Reflector, Crack, E - Replace	21,60
-------------------------------	--------------



Headlight L, Broken, E - Replace	336,00
----------------------------------	---------------



Wheel cover F R, Scratch(es), E - Replace

24,00



Wing R L, Dent(s), LI - Repair and paint (complete)

246,56



Bumper F, Crack, Le - Replace and paint

607,20



Wheel cover R R, Scratch(es), E - Replace

24,00



Door frame F L, Deformed / Strained, Forfeit

25,00



Bumper R, Deformed / Strained, Le - Replace and paint

535,20



Wing R R, Chemical pollution, LI - Repair and paint (complete)

246,56

