



**MERCEDES C COUP?: ZM8158**

Vinnumber:	<b>WDD2053401F632830</b>	Versionname:	<b>C 180</b>
First Registrationdate:	<b>26/09/2017</b>	Fiscalpower:	
Expertise Mileage:	<b>65657</b>	Power Kw:	<b>115</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metallic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Petrol</b>	Oil level:	<b>OK</b>
Maintenance:	<b>A1 DANS 220 JOURS</b>	Parking lot:	<b>3431</b>
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>2</b>		
Number of seats:	<b>4</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Seats electric F L	
GPS storage	<b>SD</b>	Seats electric F R	
GPS storage		Central consol F	
Windows electric F		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	<b>No Tow bar</b>
Alarm			
Radio multimedia			
Type of headlighting	<b>Headlighting LED</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		
Level control			
Sport seats			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/45/18/95 Y LightMetal</b>				
Summer tyres:	Fr.L.	<b>Bridgestone: 4 mm</b>	Fr.R.	<b>Bridgestone: 4 mm</b>
	Re.L.	<b>Bridgestone: 3 mm</b>	Re.R.	<b>Bridgestone: 3 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>1161,86</b>
-------------------	----------------

Windscreen, Stone chip(s), Acceptable	<b>0,00</b>
---------------------------------------	-------------

No pictures to display

Bonnet, Scratch(es), LI - Repair and paint (complete)	<b>290,08</b>
---	---------------



Bumper R, Dent(s) and scratch(es), It - Spot repair

115,56



Alloy rim R R polished, Scratch(es), Acceptable

0,00

No pictures to display

Wing F L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Bumper moulding F R, Scratch(es), E - Replace

14,40



Wing F R, Deformed / Strained, Le - Replace and paint

530,02



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Glove compartment lid, Scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Dent(s), Acceptable

0,00

No pictures to display