



FORD FOCUS : 1VKK240

| | | | |
|------------------------------------|--------------------------|--------------|------------------|
| Vinnumber: | WF0PXXGCHPJA02741 | Versionname: | |
| First Registrationdate: | 5/12/2018 | Fiscalpower: | |
| Expertise Mileage: | 24814 | Power Kw: | 74 |
| Bodytype: | | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Petrol | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 4723 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|-------------------------------|
| Windows electric F | Central consol F |
| Windows electric R | Luggage cover |
| Cruise Control | Front parking sensors |
| Steering wheel multifunctional | Rear parking sensors |
| Seats F heated | Type of Tow bar |
| Radio multimedia | No Tow bar |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Manual climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | |
|----------------------------------|-------|-------|----------------|
| 205/60/16/96 V LightMetal | | | |
| Summer tyres: | Fr.L. | Fr.R. | Michelin: 5 mm |
| | Re.L. | Re.R. | Michelin: 5 mm |

Assistance equipment

| | | | |
|--|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

| | |
|--|---------------|
| Total cost ex VAT | 327,36 |
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 211,80 |



Rear spoiler, Dent(s), LI - Repair and paint (complete)

115,56

