



MINI : 1PCY563

| | | | |
|-----------------------------------|--------------------------|--------------|------------------|
| Vinnumber: | WMWXN110402A17215 | Versionname: | 1.5 ONE D |
| First Registrationdate: | 7/06/2016 | Fiscalpower: | |
| Expertise Mileage: | 61919 | Power Kw: | 70 |
| Bodytype: | | Body color | Black |
| Gearbox: | MAN 6 VIT | Paint type | Metalic |
| Transmission: | Front | Rims summer | Aluminium |
| Fueltype: | Diesel | Oil level | OK |
| Maintenance | OK | Parking lot | 2120 |
| Battery functioning | Yes | | |
| Number of doors | 3 | | |
| Number of seats | 4 | | |
| Number head rests | 4 | | |
| Rims summer | Aluminium | | |
| Category | Passenger Car | | |
| Oil level | OK | | |
| Registration Certificate Car (BE) | Yes | | |

Options

| | |
|-------------------------|-------------------------------|
| Windows electric F | Luggage cover |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Manual climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|----------------------|-------|----------------------|
| 175/65/15/84 H LightMetal | | | | |
| Summer tyres: | Fr.L. | Hankook: 4 mm | Fr.R. | Hankook: 4 mm |
| | Re.L. | Hankook: 5 mm | Re.R. | Hankook: 5 mm |

Assistance equipment

| | | | |
|--------------------------------------------|------------|------------|----------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 1130,30 |
| Bumper grille, Dent(s), E - Replace | | | 32,40 |



Wing R L, Chemical polution, LI - Repair and paint (complete)

308,20



Wing R R, Chemical polution, LI - Repair and paint (complete)

308,20



Roof, Chemical polution, LI - Repair and paint (complete)

481,50

