


PEUGEOT 508 SW: NE4396

Vinnumber:	VF38URHC8FL014829	Versionname:	2.0 HDI 147KW S/S 4WD RXH HYBRIDE
First Registrationdate:	31/03/2015	Fiscalpower:	
Expertise Mileage:	146657	Power Kw:	147
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4327
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Seats electric F R	
GPS storage		Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Head-up Display			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	NOT OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear






	245/45/18/100 Y LightMetal			
Summer tyres:	Fr.L.	Michelin: 2 mm	Fr.R.	Michelin: 2 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	940,64
Tailgate, Scratch(es), Acceptable	0,00

No pictures to display

Door R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00
	
Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Stone chip(s), E - Replace	560,64
	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)	95,00
	
Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
	
Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00
	
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	