



PEUGEOT 5008: 1RHX633

| | | | |
|------------------------------------|-------------------------|--------------|---|
| Vinnumber: | VF30EAHVMS240860 | Versionname: | 2.0 BLUEHDI S&S 100KW ALLURE |
| First Registrationdate: | 2/01/2017 | Fiscalpower: | |
| Expertise Mileage: | 176233 | Power Kw: | 100 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 4207 |
| Number of doors: | 5 | | |
| Number of seats: | 7 | | |
| Number head rests: | 7 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|-------------------------|------------------------------|-----------------------|-------------------|
| Radio CD | | Seats electric F L | |
| Windows electric F | | Panoramic roof | |
| Windows electric R | | Luggage cover | |
| Cruise Control | | Front parking sensors | |
| Seats F heated | | Rear parking sensors | |
| Radio multimedia | | Type of Tow bar | No Tow bar |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |
| Head-up Display | | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| 215/50/17/95 V LightMetal | | | | |
| Summer tyres: | Fr.L. | Continental: 2 mm | Fr.R. | Continental: 2 mm |
| | Re.L. | Continental: 4 mm | Re.R. | Continental: 4 mm |

Assistance equipment

| | |
|--|----------|
| Number of charging cables (normal) | 0 |
| Number of charging cables (rapid charge) | 0 |

| | |
|--|--------------|
| Total cost ex VAT | 95,00 |
| Alloy rim R R, Scratch(es), LI - Repair and paint (complete) | 95,00 |



| | |
|--|------|
| Alloy rim F R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Alloy rim R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Rearview mirror housing R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |