


RENAULT CLIO: 1LGA637

Vinnumber:	VF15RJL0H53251648	Versionname:	1.5 ENERGY DCI 90E EXPRESSION
First Registrationdate:	18/09/2015	Fiscalpower:	
Expertise Mileage:	114218	Power Kw:	66
Bodytype:		Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2113
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/92 T Steel			
Winter tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1908,39
Door panel F R, Tear, Smart repair	110,64



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Headlight R, Scratch(es), Acceptable

0,00



Bodywork, Glue residues, Acceptable

0,00



Wheel cover R R, Scratch(es), E - Replace

24,00



Door R L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

169,44



Wheel cover F R, Deformed / Strained, E - Replace

24,00



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

248,40



Wheel cover R L, Scratch(es), E - Replace

24,00



Trunk lid covering R, Scratch(es), Acceptable

0,00

No pictures to display

Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)

241,34



Door R R, Dent(s), PDR - Paintless dent repair

63,00



Wing F R, Crack, Le - Replace and paint




448,01



Wheel cover F L, Broken, E - Replace

24,00



Door F R, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	246,56
	
Windscreen, Stone chip(s), Acceptable	0,00
	
Bonnet, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	169,44
	
Wing F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	