



PEUGEOT 5008: 1FQH845

Vinnumber:	VF30A9HD8DS170689	Versionname:	5008 Allure FAP 115PK
First Registrationdate:	23/09/2013	Fiscalpower:	
Expertise Mileage:	124588	Power Kw:	84
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2410
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Panoramic roof	
GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/50/17/95 W LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		


Total cost ex VAT	716,36
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80



Gear shift lever knob, Worn, E - Replace 114,00



Rocker panel inner R R, Dent(s), LI - Repair and paint (complete) 115,56



Door seal F L, Broken, E - Replace 54,00



Door R R, Dent(s), Acceptable 0,00

No pictures to display Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display Door F R, Dent(s), PDR - Paintless dent repair 63,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Dent(s), Acceptable 0,00

No pictures to display Wing F R, Scratch(es), Acceptable 0,00

No pictures to display Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display Wing R L, Dent(s), PDR - Paintless dent repair 63,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display