



**PEUGEOT Expert: 1EIG443**

Vinnumber:	<b>VF3XS9HM0CZ050880</b>	Versionname:	<b>EXPERT B/F SWB 227 L1H1 90PK</b>
First Registrationdate:	<b>12/12/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>91432</b>	Power Kw:	<b>66</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3205</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>No GPS</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>215/65/15/102 T Steel</b>			
Summer tyres:	Fr.L. <b>Michelin: 5 mm</b>	Fr.R. <b>Michelin: 5 mm</b>	
	Re.L. <b>Michelin: 5 mm</b>	Re.R. <b>Michelin: 5 mm</b>	

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT 1029,30

Steering wheel, Worn, Acceptable 0,00



Bumper F, Scratch(es), Smart repair 110,64



Ignition key, Worn, Acceptable 0,00

No pictures to display

Aerial, Damaged, E - Replace 11,25



Ignition key, Missing, E - Replace 150,00

No pictures to display

Seat cover F L, Deformed / Strained, Acceptable 0,00

No pictures to display

Trunk door R R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete) 231,15



Roof, Scratch(es), LI - Repair and paint (complete) 361,13



Wing F R, Scratch(es), LI - Repair and paint (complete) 165,13

