



**VOLKSWAGEN GOLF VII: 1LNJ919**

Vinnumber:	<b>WVWZZZAUZGP049550</b>	Versionname:	<b>2.0 TDI 110KW HIGHLINE</b>
First Registrationdate:	<b>28/10/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>158144</b>	Power Kw:	<b>110</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metallic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4510</b>
Maintenance:	<b>26600KM</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>SD</b>	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		
Adaptive cruise control			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/45/17/91 Y LightMetal</b>			
Summer tyres:	Fr.L. <b>BF Goodrich: 5 mm</b>	Fr.R. <b>BF Goodrich: 5 mm</b>	
	Re.L. <b>BF Goodrich: 4 mm</b>	Re.R. <b>BF Goodrich: 4 mm</b>	

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>
-----------------------	------------

Total cost ex VAT	<b>562,00</b>
-------------------	---------------

Backrest cover F L, Worn, Acceptable	<b>0,00</b>
--------------------------------------	-------------



Steering wheel, Worn, Acceptable

0,00



Bumper F, Scratch(es), Acceptable

0,00



Tailgate, Not original part, Sticker removal

0,00



Roof, Dent(s), PDR - Paintless dent repair

82,80



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Door R R, Scratch(es), Acceptable

0,00



Sill outer R, Scratch(es), Acceptable

0,00



Trunk lid covering R, Scratch(es), Smart repair

110,64



Alloy rim R L, Scratch(es), Acceptable

0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Door R L, Dent(s), PDR - Paintless dent repair

63,00



Door F R, Scratch(es), Acceptable

0,00



Alloy rim R R, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), It - Spot repair

115,56

