


**VOLKSWAGEN Touran: 1HNZ733**

Vinnumber:	<b>WVGZZZ1TZFW018982</b>	Versionname:	<b>TOURAN Trendline BMT St/St 7pl/DSG 105PK</b>
First Registrationdate:	<b>2/09/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>163311</b>	Power Kw:	<b>77</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1117</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Sun Roof electric	
Windows electric F	Panoramic roof	
Windows electric R	Central consol F	
Cruise Control	Luggage cover	
Steering wheel multifunctional	Front parking sensors	
Seats F heated	Rear parking sensors	
Radio multimedia	Type of Tow bar	<b>No Tow bar</b>
Type of headlighting	<b>Headlighting Xenon</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/91 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>0</b>

<b>Total cost ex VAT</b>	<b>241,56</b>
--------------------------	---------------

<b>Alloy rim F L polished, Rust, Acceptable</b>	<b>0,00</b>
---	-------------

*No pictures to display*

<b>Alloy rim R L polished, Rust, Acceptable</b>	<b>0,00</b>
---	-------------

*No pictures to display*

<b>Bumper R, Scratch(es), It - Spot repair</b>	<b>115,56</b>
--	---------------



Door R L, Dent(s), PDR - Paintless dent repair	63,00
--	-------



Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Alloy rim F R polished, Scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Xenon headlight L, Waterinfiltration, Acceptable	0,00
--	------

*No pictures to display*

Door R R, Dent(s), PDR - Paintless dent repair	63,00
--	-------

