



BMW 2 ACTIVE TOURER: 1KFN669

Vinnumber:	WBA2B31010V381134	Versionname:	1.5 216D ACTIVE TOURER
First Registrationdate:	22/04/2015	Fiscalpower:	
Expertise Mileage:	74920	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OVER 4100 KM	Parking lot:	2127
Maintenance:	1/04/2020		
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 V LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 864,80

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00





Rearview mirror housing R, Scratch(es), Smart repair

110,64



Bodywork, Dirty, P - Check

0,00



Bumper R, Scratch(es), LI - Repair and paint (partial)

211,80



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper grille, Deformed / Strained, Forfeit

25,00



Alloy rim R R, Scratch(es), Acceptable

0,00



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56

