



VOLVO V60: 1LPA183

Vinnumber:	YV1FW74C1G1306705	Versionname:	2.0 D2 KINETIC
First Registrationdate:	3/11/2015	Fiscalpower:	
Expertise Mileage:	60669	Power Kw:	88
Bodytype:	Break	Body color:	BLAUW
Gearbox:	MAN 6 VIT	Body color:	Dark Blue
Transmission:	Front	Paint type:	Metalic
Fueltype:	Diesel	Rims summer:	Aluminium
Maintenance:	1 MAAMD 13012 KM	Oil level:	OK
Maintenance:	OK	Parking lot:	3728
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/16/97 W LightMetal			
Summer tyres:	Fr.L. Bridgestone: 5 mm	Fr.R. Bridgestone: 5 mm	
	Re.L. Michelin: 5 mm	Re.R. Michelin: 5 mm	

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT		306,80
-------------------	--	--------

Bumper F, Scratch(es), LI - Repair and paint (complete)		211,80
---------------------------------------------------------	--	--------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--------------------------------------------------------------	-------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display