



BMW 3 GRAN TURISMO: 1LEF363

Vinnumber:	WBA8Y51090G430251	Versionname:	2.0 318D (100KW) GRAN TURISMO
First Registrationdate:	3/09/2015	Fiscalpower:	
Expertise Mileage:	112022	Power Kw:	100
Bodytype:		Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1431
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Front parking sensors	
Windows electric R	Rear parking sensors	
Cruise Control	Type of Tow bar	Tow bar fixed
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/97 Y LightMetal				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	2648,28
Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Dent(s) and scratch(es), Le - Replace and paint 530,02



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Door F R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Door panel R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), I - Repair 100,00



Tailgate, Scratch(es), It - Spot repair 115,56



Bumper R, Dent(s) and scratch(es), Le - Replace and paint 651,00



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), LI - Repair and paint (complete)

318,35



Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display