



BMW 3: 1LKJ939

Vinnumber:	WBA3D11050K366625	Versionname:	
First Registrationdate:	13/10/2015	Fiscalpower:	100
Expertise Mileage:	70125	Power Kw:	White
Bodytype:		Body color:	Metalic
Gearbox:	MAN 6 VIT	Paint type:	Aluminium
Transmission:	Back	Rims summer:	OK
Fueltype:	Diesel	Oil level:	2511
Battery functioning:	Yes	Parking lot:	
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Type of Tow bar
Windows electric R	No Tow bar
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	211,80
--------------------------	---------------

Alloy rim F R, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Alloy rim R R, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	211,80
--	---------------



Bumper F, Repaired, Acceptable

0,00

No pictures to display