



BMW 3 BERLINE: 1LGS715

Vinnumber:	WBA8C31040K387731	Versionname:	2.0 318D (100KW) BERLINE
First Registrationdate:	23/09/2015	Fiscalpower:	
Expertise Mileage:	64048	Power Kw:	100
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance	24000KM OF 9-2020	Parking lot:	1313
Maintenance	OK		
Battery functioning	Yes		
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage		Rear parking sensors	
GPS storage	HD	Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/96 H LightMetal				
Winter tyres:	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 203,15

Rearview mirror housing R, Scratch(es), 67 - Polish 55,19



Bumper R, Scratch(es), Acceptable

0,00



Door F L, Dent(s), Acceptable

0,00



Door panel F L, Scratch(es), Acceptable

0,00



Bumper grille, Broken, E - Replace

32,40



Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F R, Scratch(es), It - Spot repair

115,56

