



**FORD Transit 330L: 1BYD620**

Vinnumber:	<b>WF0XXXTFXCY54507</b>	Versionname:	<b>TRANS.330L B/F LWB SilverI.DPF(EU5)125PK</b>
First Registrationdate:	<b>18/01/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>312113</b>	Power Kw:	<b>92</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>LCV13</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Type of Tow bar	<b>No Tow bar</b>
GPS storage	<b>HD</b>		
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>215/75/16/113 C Steel</b>				
Summer tyres:	Fr.L.	<b>Kleber: 7 mm</b>	Fr.R.	<b>Kleber: 7 mm</b>
	Re.L.	<b>Kleber: 6 mm</b>	Re.R.	<b>Kleber: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>353,00</b>
Bodywork, Not original part, P - Check	<b>0,00</b>



Bumper F, Scratch(es), Acceptable 0,00

*No pictures to display*

Rearview mirror R complete, Broken, E - Replace 138,00



Front end, Rust, LI - Repair and paint (complete) 215,00



Rear bulkhead lining, Scratch(es), Acceptable 0,00

*No pictures to display*