



**MERCEDES CLA180: 1KAG026**

Vinnumber:	<b>WDD1173121N198497</b>	Versionname:	<b>1.5</b>
First Registrationdate:	<b>18/03/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>68772</b>	Power Kw:	<b>80</b>
Bodytype:	<b>Berline</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>2229</b>
Maintenance:	<b>B5 SERVICE OVER 123 DAGEN</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>1</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Sun Roof electric	
GPS storage		Central consol F	
GPS storage	<b>SD</b>	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	<b>No Tow bar</b>
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining semi-leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/16/91 H LightMetal</b>				
Summer tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Yokohama: 6 mm</b>	Re.R.	<b>Yokohama: 6 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>2205,07</b>
Grill frame, Deformed / Strained, E - Replace			<b>274,63</b>



Bumper R, Scratch(es), It - Spot repair 115,56



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 366,35




Alloy rim R L, Scratch(es), Acceptable 0,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 404,20



Interior, Dirty, Cleaning 150,00



Door R R, Dent(s), Acceptable 0,00



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 364,18



Door F L, Scratch(es), LI - Repair and paint (complete)

318,35

