



FORD MONDEO: 1LNE921

Vinnumber:	WF0EXXWPCEFU03731	Versionname:	1.5 TDCI 85KW S/S ECONETIC BUSINESS ED+
First Registrationdate:	27/10/2015	Fiscalpower:	
Expertise Mileage:	162045	Power Kw:	88
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	PARKING A12
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/16/95 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 2 mm	Fr.R.	Michelin: 2 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 820,02

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Repaired, Acceptable 0,00

No pictures to display



Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Floor covering F L, Hole, Smart repair	64,32



Protection plate M, Deformed / Strained, E - Replace	74,00
--	-------



Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Roof, Dent(s), PDR - Paintless dent repair	63,00



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)	310,50
---	--------

