


MAZDA 6: 1HCS819

Vinnumber:	JMZGJ691621160392	Versionname:	6 BRE Executive 150PK
First Registrationdate:	19/06/2014	Fiscalpower:	
Expertise Mileage:	148976	Power Kw:	110
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2426
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	Tow bar fixed
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/19/96 V LightMetal			
Winter tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm

Assistance equipment

Spare wheel	Yes	Compressor	Yes
Repair kit	Yes		
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	980,58
Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Scratch(es), LI - Repair and paint (complete) 290,08



Sill outer R, Dent(s), LI - Repair and paint (complete) 310,50

