



RENAULT CAPTUR: 1KJN655

Vinnumber:	VF12R5A1H53047534	Versionname:	0.9 TCE 90 ENERGY ZEN ECO2
First Registrationdate:	12/05/2015	Fiscalpower:	
Expertise Mileage:	59712	Power Kw:	66
Bodytype:		Body color:	Orange
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1233
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 H LightMetal				
Winter tyres:	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT		363,64
-------------------	--	---------------

Door F R, Scratch(es), Acceptable		0,00
-----------------------------------	--	-------------

No pictures to display

Rear window, Scratch(es), E - Replace		0,00
---------------------------------------	--	-------------



Wing F R, Bad repair, Acceptable 0,00



Seat cover F L, Worn, Acceptable 0,00



Tailgate, Scratch(es), 67 - Polish 0,00

No pictures to display

Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Dent(s), PDR - Paintless dent repair 63,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Chemical polution, 67 - Polish 0,00

No pictures to display

Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper R, Scratch(es), Smart repair	110,64
-------------------------------------	--------



Roof, Dent(s), Acceptable	0,00
---------------------------	------

No pictures to display