



**MINI : 1PCY493**

Vinnumber:	<b>WMWXN110803851767</b>	Versionname:	<b>1.5 ONE D</b>
First Registrationdate:	<b>7/06/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>52610</b>	Power Kw:	<b>70</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4622</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>3</b>		
Number of seats:	<b>4</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Windows electric F	Luggage cover
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>175/65/15/94 H LightMetal</b>				
Summer tyres:	Fr.L.	<b>Dunlop: 4 mm</b>	Fr.R.	<b>Dunlop: 4 mm</b>
	Re.L.	<b>Dunlop: 5 mm</b>	Re.R.	<b>Dunlop: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	3241,88
-------------------	---------

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Door F L, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Roof, Chemical pollution, LI - Repair and paint (complete)			481,50
Wing trim R R, Scratch(es), E - Replace			84,00
Tailgate, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door F R, Scratch(es), LI - Repair and paint (complete)			318,35
Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)			356,20
Wing R R, Dent(s), LI - Repair and paint (complete)			452,20
Rear window, Scratch(es), E - Replace			370,00
Windscreen, Scratch(es), E - Replace			487,20
Wing trim R L, Scratch(es), E - Replace			84,00