



PEUGEOT PARTNER: 1LFB563

Vinnumber:	VF37B9HN0FN529199	Versionname:	1.6 HDI 120 L1H1 55KW PACK CD AIRCO
First Registrationdate:	10/09/2015	Fiscalpower:	
Expertise Mileage:	38403	Power Kw:	55
Bodytype:		Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2701
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Type of Tow bar	No Tow bar
Windows electric F		
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/65/15/91 T Steel				
Summer tyres:	Fr.L.	Other: 6 mm	Fr.R.	Other: 6 mm
	Re.L.	Other: 7 mm	Re.R.	Other: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 603,15

Bodywork, Not original part, Acceptable 0,00





Wing F L, Dent(s) and scratch(es), Le - Replace and paint

427,51



Rearview mirror housing L, Scratch(es), Smart repair

110,64



Interior, Stain, Cleaning

25,00



Protection plate M, Hole, E - Replace

40,00

