



PEUGEOT 508 SW: 1SGS637

| | | | |
|------------------------------------|--------------------------|--------------|--------------------------------------|
| Vinnumber: | VF38EAHXMHL012472 | Versionname: | 2.0 BlueHDi 110kW S/S GT Line |
| First Registrationdate: | 9/05/2017 | Fiscalpower: | |
| Expertise Mileage: | 76890 | Power Kw: | 110 |
| Bodytype: | Break | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metallic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3821 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | |
|--------------------------------|------------------------------|-------------------|
| Radio CD | Panoramic roof | |
| Windows electric F | Central consol F | |
| Windows electric R | Luggage cover | |
| Cruise Control | Front parking sensors | |
| Steering wheel multifunctional | Rear parking sensors | |
| Radio multimedia | Type of Tow bar | No Tow bar |
| Type of headlighting | Headlighting LED | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining semi-leather | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|----------------|-------|----------------|
| Winter tyres: | 235/45/18/98 Y LightMetal | | | |
| | Fr.L. | Michelin: 7 mm | Fr.R. | Michelin: 7 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

Assistance equipment

| | | | |
|-----------------------|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
|-----------------------|------------|------|------------|

| | |
|--|------|
| Total cost ex VAT | 0,00 |
| Bonnet, Stone chip(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Alloy rim F R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Rear window, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |