



## TOYOTA YARIS: 1RU577

Vinnumber:	VNKKD3D300A319399	Versionname:	1.5 VVT-i Hybrid Style
First Registrationdate:	8/03/2017	Fiscalpower:	
Expertise Mileage:	58147	Power Kw:	54
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1208
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

## Options

GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

## Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

## Degree of wear

	195/50/16/88 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

## Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	649,64
-------------------	--------

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rearview mirror R complete, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Rear window, Scratch(es), E - Replace	0,00
---------------------------------------	------



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), 67 - Polish 0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete) 385,20



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Chemical polution, 67 - Polish 0,00

No pictures to display