



VOLVO V40: 1HZK982

Vinnumber:	YV1MZ8451F2067829	Versionname:	V40 Cr.Country D2 Base 115PK
First Registrationdate:	6/11/2014	Fiscalpower:	
Expertise Mileage:	99797	Power Kw:	84
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3415
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Panoramic roof
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/98 W LightMetal				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	385,08
--------------------------	---------------

Bumper F, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Alloy rim R L polished, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Alloy rim F L polished, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

No pictures to display

Bonnet, Scratch(es), LI - Repair and paint (complete) 290,08



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Roof pillar R, Bad repair, Acceptable 0,00



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer R, Bad repair, Acceptable 0,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display