



VOLKSWAGEN Golf: 1JVC744

Vinnumber:	WVWZZZAUZFP035274	Versionname:	GOLF BER Trendline 105PK
First Registrationdate:	4/03/2015	Fiscalpower:	
Expertise Mileage:	137370	Power Kw:	77
Bodytype:		Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1713
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	SD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/65/15/92 H Steel				
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1577,38
GPS, Crack, E - Replace	690,20



Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Floor covering F L, Burned, E - Replace 252,00



Seat cover F L, Stain, Cleaning 25,00



Wheel cover F R, Scratch(es), E - Replace 30,00



Seat cover R L, Burned, E - Replace 360,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Dent(s), LI - Repair and paint (complete) 220,18

