


**BMW 2 ACTIVE TOURER: 1LNY725**

|                                   |                          |              |                               |
|-----------------------------------|--------------------------|--------------|-------------------------------|
| Vinnumber:                        | <b>WBA2B31060V651930</b> | Versionname: | <b>1.5 216D ACTIVE TOURER</b> |
| First Registrationdate:           | <b>2/11/2015</b>         | Fiscalpower: |                               |
| Expertise Mileage:                | <b>108367</b>            | Power Kw:    | <b>85</b>                     |
| Bodytype:                         |                          | Body color   | <b>White</b>                  |
| Gearbox:                          | <b>Automatic</b>         | Paint type   | <b>Opaque</b>                 |
| Transmission:                     | <b>Front</b>             | Rims summer  | <b>Aluminium</b>              |
| Fueltype:                         | <b>Diesel</b>            | Oil level    | <b>OK</b>                     |
| Battery functioning               | <b>Yes</b>               | Parking lot  | <b>2825</b>                   |
| Number of doors                   | <b>5</b>                 |              |                               |
| Number of seats                   | <b>5</b>                 |              |                               |
| Number head rests                 | <b>5</b>                 |              |                               |
| Rims summer                       | <b>Aluminium</b>         |              |                               |
| Category                          | <b>Passenger Car</b>     |              |                               |
| Oil level                         | <b>OK</b>                |              |                               |
| Registration Certificate Car (BE) | <b>Yes</b>               |              |                               |

**Options**

|                                |                                  |                      |                   |
|--------------------------------|----------------------------------|----------------------|-------------------|
| GPS storage                    |                                  | Central consol F     |                   |
| GPS storage                    | <b>HD</b>                        | Luggage cover        |                   |
| Windows electric F             |                                  | Rear parking sensors |                   |
| Windows electric R             |                                  | Type of Tow bar      | <b>No Tow bar</b> |
| Cruise Control                 |                                  |                      |                   |
| Steering wheel multifunctional |                                  |                      |                   |
| Radio multimedia               |                                  |                      |                   |
| Type of headlighting           | <b>Headlighting Halogen</b>      |                      |                   |
| Type of GPS                    | <b>GPS big screen color</b>      |                      |                   |
| Type of Lining                 | <b>Lining artificial leather</b> |                      |                   |
| Type of climate control        | <b>Autom climate control</b>     |                      |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                          |       |                          |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
|               | <b>205/60/16/92 H LightMetal</b> |                          |       |                          |
| Winter tyres: | Fr.L.                            | <b>Continental: 6 mm</b> | Fr.R. | <b>Continental: 6 mm</b> |
|               | Re.L.                            | <b>Continental: 6 mm</b> | Re.R. | <b>Continental: 6 mm</b> |

**Assistance equipment**

|                                          |            |            |            |
|------------------------------------------|------------|------------|------------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |            |            |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |

|                                   |                |
|-----------------------------------|----------------|
| Total cost ex VAT                 | <b>1005,80</b> |
| Bonnet, Stone chip(s), Acceptable | <b>0,00</b>    |



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Windscreen, Stone chip(s), E - Replace

487,20



Alloy rim R R, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Seat cover F L, Worn, Acceptable

0,00



Alloy rim F R, Scratch(es), Acceptable

0,00

*No pictures to display*