



AUDI A5 SPORTBACK: PK8664

Vinnumber:	WAUZZZ8T3GA022060	Versionname:	3.0 TDI 160KW S TRONIC QUATTRO S LINE
First Registrationdate:	1/10/2015	Fiscalpower:	
Expertise Mileage:	94703	Power Kw:	160
Bodytype:		Body color	Black
Gearbox:	Automatic	Paint type	Metalic
Transmission:	4 Weel	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4305
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Seats R heated	
GPS storage		Central consol F	
GPS storage	HD	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar removable
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	255/55/19/96 Y LightMetal			
Summer tyres:	Fr.L.	Michelin: 2 mm	Fr.R.	Michelin: 2 mm
	Re.L.	Michelin: 2 mm	Re.R.	Michelin: 2 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1466,12
-------------------	----------------

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Wing F R, Scratch(es), 67 - Polish	0,00
------------------------------------	-------------

No pictures to display

Bonnet, Stone chip(s), Acceptable	0,00
  	
Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
     	
Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00
     	
Door R R, Bad repair, Acceptable	0,00
 	
Bumper F, Scratch(es), LI - Repair and paint (complete)	254,16
    	
Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
   	
Sill outer L, Scratch(es), 67 - Polish	0,00
No pictures to display	
Door F R, Scratch(es), Acceptable	0,00
No pictures to display	
Sill outer R, Dent(s), Acceptable	0,00
No pictures to display	

Rearview mirror housing L, Scratch(es), Acceptable		0,00
No pictures to display		
Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)		95,00
		
Roof, Chemical pollution, LI - Repair and paint (complete)		577,80
		
Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)		95,00
		
Wing R R, Bad repair, Acceptable		0,00
		