


BMW 2 GRAN TOURER: 1LVB920

Vinnumber:	WBA2E510605C91824	Versionname:	2.0 218D (100KW) GRAN TOURER
First Registrationdate:	14/12/2015	Fiscalpower:	
Expertise Mileage:	117074	Power Kw:	100
Bodytype:		Body color	Red
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2719
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage	HD	Seats electric F L	
GPS storage		Seats electric F R	
Windows electric F		Sun Roof electric	
Windows electric R		Panoramic roof	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Head-up Display			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	205/55/17/95 H LightMetal			
	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT		1561,21
Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)		95,00



Roof, Chemical polution, LI - Repair and paint (complete)

481,50



Rear window, Scratch(es), Acceptable

0,00



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Door seal F L, Deformed / Strained, E - Replace

54,00



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Bonnet, Chemical polution, 67 - Polish

0,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R L, Scratch(es), Acceptable	0,00
No pictures to display	
Door F R, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00



Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Door R R, Scratch(es), Acceptable	0,00
No pictures to display	
Rear spoiler, Chemical pollution, LI - Repair and paint (complete)	115,56



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Bumper F, Scratch(es), Acceptable	0,00
No pictures to display	