



BMW 3 TOURING: 1KRZ794

Vinnumber:	WBA3K110X0K568611	Versionname:	2.0 318D (100KW) TOURING
First Registrationdate:	19/06/2015	Fiscalpower:	
Expertise Mileage:	105222	Power Kw:	100
Bodytype:		Body color	Black
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4713
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Sun Roof electric
GPS storage	Panoramic roof
GPS storage	HD Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/60/16/92 W LightMetal			
	Fr.L.	Hankook: 4 mm	Fr.R.	Hankook: 4 mm
	Re.L.	Hankook: 3 mm	Re.R.	Hankook: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1675,83
-------------------	---------

Door F L, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Roof, Scratch(es), 67 - Polish	0,00
--------------------------------	------

No pictures to display


Alloy rim F L, Scratch(es), Acceptable	0,00
No pictures to display	
Door F R, Scratch(es), Acceptable	0,00
No pictures to display	
Sill outer R, Scratch(es), LI - Repair and paint (complete)	310,50
	
Wing R L, Scratch(es), 67 - Polish	0,00
No pictures to display	
Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20
	
Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
	
Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)	211,80
	



Bonnet, Scratch(es), 67 - Polish	0,00
----------------------------------	------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Windscreen, Stone chip(s), Acceptable	0,00
---------------------------------------	------



Tailgate, Scratch(es), 67 - Polish	0,00
------------------------------------	------

No pictures to display

Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	220,18
---	--------



Door R L, Scratch(es), 67 - Polish	0,00
------------------------------------	------

No pictures to display