


**BMW 1 HATCH: 1KPF183**

|                                   |                          |              |                                                |
|-----------------------------------|--------------------------|--------------|------------------------------------------------|
| Vinnumber:                        | <b>WBA1V910405B16135</b> | Versionname: | <b>1.5 116D EFFICIENTDYNAMICS EDIT. (85KW)</b> |
| First Registrationdate:           | <b>9/06/2015</b>         | Fiscalpower: |                                                |
| Expertise Mileage:                | <b>103408</b>            | Power Kw:    | <b>85</b>                                      |
| Bodytype:                         |                          | Body color   | <b>Black</b>                                   |
| Gearbox:                          | <b>MAN 6 VIT</b>         | Paint type   | <b>Metallic</b>                                |
| Transmission:                     | <b>Back</b>              | Rims summer  | <b>Aluminium</b>                               |
| Fueltype:                         | <b>Diesel</b>            | Oil level    | <b>OK</b>                                      |
| Maintenance                       | <b>OK</b>                | Parking lot  | <b>4820</b>                                    |
| Maintenance                       | <b>BINNEN 18000KM</b>    |              |                                                |
| Battery functioning               | <b>Yes</b>               |              |                                                |
| Number of doors                   | <b>5</b>                 |              |                                                |
| Number of seats                   | <b>5</b>                 |              |                                                |
| Number head rests                 | <b>5</b>                 |              |                                                |
| Rims summer                       | <b>Aluminium</b>         |              |                                                |
| Category                          | <b>Passenger Car</b>     |              |                                                |
| Oil level                         | <b>OK</b>                |              |                                                |
| Registration Certificate Car (BE) | <b>Yes</b>               |              |                                                |

**Options**

|                                |                                |
|--------------------------------|--------------------------------|
| Radio CD                       | Central consol F               |
| GPS storage                    | Luggage cover                  |
| GPS storage                    | <b>HD</b> Rear parking sensors |
| Windows electric F             |                                |
| Windows electric R             |                                |
| Cruise Control                 |                                |
| Steering wheel multifunctional |                                |
| Radio multimedia               |                                |
| Type of headlighting           | <b>Headlighting Halogen</b>    |
| Type of GPS                    | <b>GPS big screen color</b>    |
| Type of Lining                 | <b>Lining fabrics</b>          |
| Type of climate control        | <b>Manual climate control</b>  |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>205/55/16/91 H LightMetal</b> |                       |       |                       |
| Winter tyres: | Fr.L.                            | <b>Goodyear: 5 mm</b> | Fr.R. | <b>Goodyear: 5 mm</b> |
|               | Re.L.                            | <b>Goodyear: 7 mm</b> | Re.R. | <b>Goodyear: 7 mm</b> |

**Assistance equipment**

|                                                              |            |            |               |
|--------------------------------------------------------------|------------|------------|---------------|
| Repair kit                                                   | <b>Yes</b> | Compressor | <b>Yes</b>    |
| Total cost ex VAT                                            |            |            | <b>190,00</b> |
| Door F R, Dent(s), Acceptable                                |            |            | <b>0,00</b>   |
| <i>No pictures to display</i>                                |            |            |               |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) |            |            | <b>95,00</b>  |



|                                                              |       |
|--------------------------------------------------------------|-------|
| Door R R, Dent(s), Acceptable                                | 0,00  |
| <i>No pictures to display</i>                                |       |
| Interior, No damage, No repair                               | 0,00  |
| <i>No pictures to display</i>                                |       |
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete) | 95,00 |

