


BMW 2 ACTIVE TOURER: 1LSN387

Vinnumber:	WBA2B31020V690885	Versionname:	1.5 216D ACTIVE TOURER
First Registrationdate:	24/11/2015	Fiscalpower:	
Expertise Mileage:	88244	Power Kw:	85
Bodytype:		Body color	Brown
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	2102
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Rear parking sensors
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/55/17/92 H LightMetal			
	Fr.L.	Hankook: 3 mm	Fr.R.	Hankook: 3 mm
	Re.L.	Hankook: 4 mm	Re.R.	Hankook: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	942,70
Door R R, Scratch(es), LI - Repair and paint (complete)	318,35



Door seal F L, Broken, E - Replace		54,00
		
Bumper R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)		95,00
		
Door F R, Scratch(es), LI - Repair and paint (complete)		318,35
		
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)		95,00
		
Alloy rim F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Protection plate M, Tear, E - Replace		62,00
		