



BMW 3 TOURING: 1LRN963

Vinnumber:	WBA8L71030K555964	Versionname:	2.0 316D (85KW) TOURING
First Registrationdate:	16/11/2015	Fiscalpower:	
Expertise Mileage:	130880	Power Kw:	85
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	1404
Maintenance	26000		
Maintenance	OKTOBER 2020		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/60/16/92 V LightMetal			
	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT		32,40
-------------------	--	--------------

Internal Boot Lining R, Scratch(es), Acceptable		0,00
---	--	-------------

No pictures to display		
------------------------	--	--

Outer backrest protection L, Scratch(es), Acceptable		0,00
--	--	-------------

No pictures to display		
------------------------	--	--

Bumper F, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper grille, Broken, E - Replace	32,40
   	
Maintenance book, Missing, Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Seat F L compl, Worn, Acceptable	0,00
<i>No pictures to display</i>	
Bodywork, Not original part, Acceptable	0,00
	
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Trunk lid covering R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Internal Boot Lining L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	