



Peugeot 508: 1DWL868			
Vinnumber:	VF38DRHR8CL069968	Versionname:	
First Registrationdate:	18/09/2012	Fiscalpower:	
Expertise Mileage:	185680	Power Kw:	100
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1309
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options			
Radio CD		Central consol F	
GPS storage	HD	Front parking sensors	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
	215/60/16/95 V LightMetal		
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.
	Re.L.	Michelin: 4 mm	Re.R.

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		
Total cost ex VAT			1910,21
Door panel F L, Worn, Acceptable			0,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Steering wheel, Worn, Acceptable 0,00




Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Roof, Scratch(es), LI - Repair and paint (complete) 481,50



Bonnet, Scratch(es), LI - Repair and paint (complete) 290,08





Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing F L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Wing F R, Scratch(es), Acceptable

0,00

No pictures to display