



FORD C-MAX: 1KLE676			
Vinnumber:	WF0JXXGCBJFC08780	Versionname:	DIESEL
First Registrationdate:	26/05/2015	Fiscalpower:	
Expertise Mileage:	57319	Power Kw:	85
Bodytype:	Hatchback	Body color	Brown
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2630
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	215/55/16/93 V LightMetal			
	Fr.L.	Vredestein: 6 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Vredestein: 7 mm	Re.R.	Vredestein: 7 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			1622,87
Door R R, Scratch(es), Acceptable			0,00



Bumper F, Not original part, Acceptable

0,00



Door F L, Scratch(es), Acceptable

0,00



Alloy rim R L polished, Scratch(es), Acceptable

0,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F, Scratch(es), Acceptable

0,00



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Maintenance book, Missing, P - Check

0,00



Wing R R, Scratch(es), It - Spot repair

115,56



Grill, Broken, E - Replace

343,63



Wing F R, Scratch(es), LI - Repair and paint (complete)

220,18



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Door panel F L, Scratch(es), Acceptable

0,00

