


OPEL Astra: 1FWY773

Vinnumber:	W0LPD8EW6E8019870	Versionname:	ASTRA BRE ecoFL Enjoy Active St/St 110PK
First Registrationdate:	22/11/2013	Fiscalpower:	
Expertise Mileage:	183685	Power Kw:	81
Bodytype:		Body color	Silver
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3105
Number of doors	5		
Number of seats	5		
Number head rests	4		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Rear parking sensors	
Windows electric F	Type of Tow bar	Tow bar fixed
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	No GPS	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	215/60/16/99 T Steel			
	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	962,75
Bonnet, Deformed / Strained, LI - Repair and paint (complete)	290,08



Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Door panel F R, Scratch(es), Acceptable	0,00



Tailgate, Scratch(es), Acceptable	0,00
No pictures to display	
Floor covering F L, Hole, Smart repair	64,32



Wing F L, Scratch(es), Acceptable	0,00
No pictures to display	
Rear bulkhead lining, Missing, E - Replace	20,00



Wheel cover F L, Scratch(es), Acceptable	0,00
No pictures to display	
Door R R, Scratch(es), Acceptable	0,00
No pictures to display	
Door panel F L, Scratch(es), Acceptable	0,00



Luggage space cover, Missing, E - Replace	240,00
---	--------



Wheel cover F R, Scratch(es), E - Replace	30,00
---	-------



Door F R, Deformed / Strained, LI - Repair and paint (complete)

318,35



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display